7	day, 1/15/2008 3:07:56 PM			/
	day, 1/10/2006 3.07.56 PM Johnston	Process Sheet		Q
Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: 412 X-TUBE ,LOW NARBO	ว์W AFT
Customer Job Number	: 36768			
Estimate Number	: 13020.		•	
P.O. Number	:	Part Number	: D412664209	
This Issue	: 1/15/2008 S.O. No. :	Drawing Number	: D412-664-209 U#R- 🗘	10
Prsht Rev.	: NC	Project Number	: N/A	(1) AR. 23 15
First Issue	: 1/15/2008	R Drawing Revision	: UAR-A	01 88-011)
Previous Run	: 34754	Material	:	
Written By		Due Date	: 2/4/2008 Qty :	1 Um: Each
Checked & Approv	/ed By : 79 08 0) 5			
Comment	: Est Rev:A New Issue 07.09.12	EC verified by: JLM		
. •	Est Rev:B ECN 1100 08-01-11	DD verified by EC		
Additional Product	•			
Additional Froduct	•			
		•		,
	(
Job Number:				
Seq. #:	Machine Or Operation:	Description :		
1.0	DC	DOCUMENT CONTROL		
1.0		3000 <u>-</u>		
•				
Comme	ent: DOCUMENT CONTROL		1 188118 18181 41811 1881 1881	(t).
· ·	Photocopy bluefile and create labels as p	ner PPP D212-664-209 CHG001	KJ 08:0	11.29
2.0	D6008132P	Crosstube extrusion	19000	J(1)
مند				1
i onbi24		•		
DleOok 29 Comme	ent: Qty.: 1.0000 Each(s)/Unit Total :	1.0000 Each(s)	(11111111111111111111111111111111111111	
00111111	Pick:	1.0000 Edon(0)	••	
	Qty Part number Description Batch			·
	1 D6008-132 Crosstube B 26.55	18		
	Check OD = 3.250"; ID = 2.375"	رحی ۱، ۱	1 90 4	_
20		MORI SEIKI CNC LATHE LARGE	nter BG 08.	0(.10
, 3.0	MORI SEIKI 	WORLSEIN ONG LATTIL LANGE	1 14 1 14 14 14 14 14 14 14 14 14 14 14	•
	111111111111111111111111111111111111111	D 440 004 040	<u>. </u>	
Comme	ent: 1-TURN AS PER FOLIO FA708 & DWG	D412-664-249,		
क्षी पं∶	FOLIO REV: 47			
	DWG REV:_A			
•	2-DEBURR AS REQUIRED		BG 08.01.1	۱ ۹ (۲)
4.0	QC2	INSPECT PARTS AS THEY COME		/
	F 0.0 F 1.0 F 1.			1
Comme	ent: INSPECT PARTS AS THEY COME OFF	MACHINE	BC 08.	91.19
5.0	QC8	SECOND CHECK		
Comme	ent: SECOND CHECK		my ollo	1/21
			7 240	· · · · · · · · · · · · · · · · · · ·

χ,

Dart Aerospace Ltd

W/O:	٠,٠	- WORK ORDER CHANGES			•		
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	, 2						
	. St. strag						

Part No: _	•.	_ PAR #: _	Fault	Category:	NCR: Yes No	DQA:	Date:	
	er en						, <u>e</u>	
	The state of the s	*			QA: N/C C	losed:	Date:	

NCR:		, * W	ORK OR	DER NON-CONFORMANCE	(NCR)		# _	
	T	Description of NC		Corrective Action Section B		Verification	Approval	Annewal
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
			\$ 15. 50.5	у1.				
					-	¥.		•
						**		

Tuesday, 1/15/2008 3:07:56 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: 412 X-TUBE ,LOW NARROW AFT Customer: CU-DAR001 Dart Helicopters Services Part Number: D412664209 * Job Number: 36768 Job Number: Description: Seq. #: Machine Or Operation: LANDING GEAR RESOURCE 1 6.0 LANDING GEAR 1 Comment: LANDING GEAR RESOURCE 1 AWM 08-01-22 1-Polish entire outside surface of crosstube INSPECT, WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP HAND FINISHING RESOURCE # Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 INSPECT WORKWING WALK QC3/5 9.0 Comment: Inspect work +& Chemical conversion Coat BENDING MACHINE BENDING 10.0 Comment: BENDING MACHINE and Folio FT Bend tube as per Dwg D412-664-249 using CNC bender program DIMENSIONAL CHECK 11.0 Comment: DIMENSIONAL CHECK CUFF 12.0 D36601 Comment: Qty.: Total: 2.0000 Each(s) 2.0000 Each(s)/Unit CUFF. Batch: <u>133665</u>1 LANDING GEAR RESOURCE 1 Comment: LANDING GEAR RESOURCE 1 1.0 Cut to height EL/JD 8-2-4
1.1-Drill Rivet holes as per Dwg D412-664-249 2-Drill pilot holes in tube as per Dwg D412-664-249 8-2-6 3-Ream hole to finish size in tube as per Dwg D412-664-249

Page 2

Dart Aerospace Ltd

W/O: -			WORK ORDER CHA	NGES				**
DATE	STEP	4	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		e.						
			•					
			∠ '		•			
Part No			AP#: Fault Catagony	NCP: Voc	N- DO	 	Deter	<u> </u>

QA: N/C Closed: ____ Date: ____

NCR:		W	ORK ORD	ER NON-CONFORMANCI	E (NCR)			
		Description of NC		Corrective Action Section B		Verification	Approval Chief Eng	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		Approva QC Inspecto
	·	· ·						
				•				
								
						:		
-								
		,						


Tuesday, 1/15/2008 3:07:56 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: 412 X-TUBE ,LOW NARROW AFT Customer: CU-DAR001 Dart Helicopters Services Part Number: D412664209 Job Number: 36768 Job Number: Description: Seq. #: Machine Or Operation: 4-Deburr & Inspect for surface damage. Repair damage within limits as per Dwg D412-664-249 HAND FINISHING RESOURCE #1 HAND FINISHING1 14.0 AWM 68-02-07 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat Tube & Cuffs as per QSI 005 4.1 INSPECT POWDER COAT/CHEMICAL CONVERSION 15.0 POWDER COAT/CHEMICAL CONVERSION Comment: INSPEC INSPECT WORK TO CURRENT STEP 16.0 QC5 **CURRENT STEP OUTSIDE SERVICES -LG OUTSIDE SERV.10** 17.0 Comment: Sub-Contracting OUTSIDE SERVICES Liquid Penetrant Inspection as per QSI 038 0208102119(1) Issue P/O: <u>5729</u> LPI as per ASTM 1417 Level 2 Attach copy of NDT results to work order PACKAGING RESOURCE #1 18.0 PACKAGING ' Comment: PACKAGING RESOURCE #1 Inspect for transit damage Ensure copy of NDT results attached to work order 19.0 QC5 WORK TO CURREN Comment: Inspect for damage & ensure results are as 20.0 Comment: LANDING GEAR RESOURCE 1 1-Rivet Cuffs as per Dwg D412-664-249. with Sika flex in Between tube & Cuff A/R, SIKAFLEX -241/-291 BATCH: МЮ 484

Dart Ae	rospace	Ltd		•					
W/O:		٠	WOI	RK ORDER CHANGE	S				
DATE	STEP	PRO	CEDURE CHAN	GE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval. QC Inspector
-						•		ŧ	
				•				•	
		·			•				•
Part No	a M	PAR #:	_ Fault Catego	ory:	NCR: Yes	No DQ	A:	Date:	•
•					QA: N	/C Close	d:	_ Date: _	
NCR:		. V	ORK ORDE	R NON-CONFORMAN	NCE (NCF	R)			o _ 4:
DATE	STEP	Description of NC Section A	Initial Chief Eng	orrective Action Section Action Description Chief Eng	B Sign 8 Date	Verific Secti	cation ion C	Approval Chief Eng	Approval QC Inspector
				L					:
				•	C	>			

Tuesday, 1/15/2008 3:07:56 PM Date: User: Kim Johnston **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: 412 X-TUBE ,LOW NARROW AFT Part Number: D412664209 Job Number: 36768 Job Number: Seq. #: Machine Or Operation: Description: CHERRY RIVET 21.0 CR3212407 44.0000 Each(s) Comment: Qty.: 44.0000 Each(s)/Unit Total: CHERRY RIVET Batch: <u>M 104 07</u> SPRAY PAINTING 22.0 Comment: SPRAY PAINTING 1-Prime inside and outside crosstube as per QSI 005 4.2 2-Paint outside crosstube with White Imrongas per QSI 005 4.2 23.0 QC14 Comment: Inspect Spray Paint Wrap in plastic bag to protect from scratches 24.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Support 25.0 D31891 Chafing Shield Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Chafing Shield 26.0 D3595 Rubber Cushion (per sq ft) Comment: Qty.: 0.0263 sf(s)0.0263 sf(s)/Unit Total: Rubber Cushion Cut to .630" X 5.70". Qty 2 08 02 Batch: 27.0 MS2192028 Clamp(per, MIL-DTL-8783C) - **\$** Comment: Qty.: Total: 4.0000 Each(s) 4.0000 Each(s)/Unit Clamp 104473 Batch:

W/O:			WORK ORDER	CHANGES .					
DATE	STEP	PF	ROCEDURE CHANGE		Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
•									
·									
Part No	:	PAR #:	Fault Category:	NCR:	Yes	No DQ	A :	_ Date: _	
		% .			QA: N	/C Closed	d:	Date:	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
	T	Description of NC		Corrective Action Section B		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
		•						
				•	٠.		-	
· · · · · · · · · · · · · · · · · · ·								
	•							
	,.					:		
				•				
				•				



Dart	Aeros	pace	Ltd
Dait	ACI US	Dave	Lu

							
W/O:		WORK ORDER CHANGE	S				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							/ _ /
Part No	:	PAR #: Fault Category:	NCR: Yes	No DQ	A: <u>42</u>	_ Date: _0	2610195
			QA:	N/C Close	d:	_ Date: _	
NOD.		WORK ORDER NON-CONFORMAN	NCF (NC	:R)			

NCR:	WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B		Verification	Annroyal	Annroyal
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
,				•				
								چ.

	sday, 1/15/2008 3:07:56 PM			
· • • • • • • • • • • • • • • • • • • •	Johnston	Process Sheet		
. Customer:	CU-DAR001 Dart Helicopters Services	Drawing Name: 4	12 X-TUBE ,LOW NARROW AFT	
` Job Number:	36768	Part Number: D	0412664209	
Job Number:				
Seq. #:	Machine Or Operation:	Desc	ription :	
	Batch:	INSPECT WORK TO CURRENT	CTED	
30 //	pt: INCREAL WORK TO CURRENT S	08 02.	·	
	nt: INSPECT WORK TO CURRENT S PACKAGING 1	PACKAGING RESOURCE #1		
37/		Dreft 8/2/07	500	
Comme	nt: HAND FINISHING RESOURCE # Identify and pack for shipping as po			
38	QC21	FINAL INSPECTION/W/O RELEA	SE	(7)
Comme	nt: FINAL INSPECTION/W/O RELEAS			2/07
Job Completion		7	408.02.27	
36. G	004 /08	orz D		
•				
				•

Dart Ae	rospace Lt	d						
W /O:			WORK ORDER (CHANGES				
DATE	STEP	PROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		•						
		2.05 						
		• · · · · · · · · · · · · · · · · · · ·						
Part No		PAR #: F	ault Category:	NCR: Yes	No DQ	A:	Date:	
							_ Date:	
NCR:		WOR	K ORDER NON-CON			-		

NCR:			WORK ORDER NON-CONFORMANCE (NCR)							
-		Description of NC		Corrective Action Section B		V16111				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector		
		v (·						
]		**		

DART AEROSPACE LTD	Work Order:	36768
Description: Crosstube Assembly (412 Low Aft)	Part Number:	D412-664-249
Inspection Dwg: D412-664-249 Rev: A		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype


lr Dra	nspection Sheet awing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
	7-680	±.010 ±.005 ±.005	2.678				
	2.680	+-005 +-005	2.684	1			
	7.687	IN:	7.689	\			
	2-793		7.796	\			
	7-930	ч	7.933	1	-		
_	3067	• •	3.070	レ			
Е	3.205	· ·	3.207	✓			
SIDE	3-358	· · ·	3. 3 59	V			
•							·
•	127.82"	± ,020"	127.840	·			
	2-680	+.00	2.678	<u>: </u>			745
	2686	+.010	2.683	<u> </u>			
	7-687	11	7.690	<u> </u>			
	2-793	L.	2.797	<u> </u>			
œ	2.930	G.	2.933	<u> </u>			A
SIDE	3-067	Ч	3.070	~			
S	3-205	u	3.209	~			
	3.358	CI.	3.359	<u> </u>			


Measured by:	Audited by:	anh,	Prototype Approval:	N/A
Date: oscolity	Date:	08/6/121	Date:	N/A

Rev	Date	Change		Revised by	Approved
Α		New Issue	(P/O D212-664-209)	KJ/EC/DD	

DART AEROSPACE LTD	Work Order:	36768
Description: Crosstube Low Aft (412)	Part Number:	D212-664-209
Inspection Dwg: D212-664-249 Rev: A		Page 1 of 1

Required Dimension	Min	Max
Height	17.78	ાક.૦૫
1/2 Span	48.55	48.81
Angle	49	52
Total Span	97.1	97.62





Rev	Date	Change	Revised by	Approved
Α		New Issue		

PARTS LIST:

Qty	Part Number	Description
X	D412-664-249	CROSSTUBE ASSEMBLY (412 LOW AFT)
1	D6009-129	CROSSTUBE
2	D2856-600-1009	ABRASION STRIP
1	D2896-1	SUPPORT
2	D3189-1	CHAFING SHIELD
2	D3595-063-570	RUBBER CUSHION
2	D3660-1	CUFF
44	CR3212-4-07	RIVET (OR M7885/3-4-07)
4	MS21920-28	CLAMP
2	MS21920-30	CLAMP (OR MS21920-32)
A/R	MAGNOBOND 6398	ROCKWELL SPECIFICATION RBO-120-023 ADHESIVE (TEXTRON/BELL SPEC. 299-947-100, TYPE II, CLASS 2 ADHESIVE)
A/R	SIKAFLEX-241/-291	SEALANT (OR PROSEAL 890 OR MIL-S-8802 CLASS B2 SEALANT)

GENERAL NOTES:

- 1) MATERIAL: MANUFACTURED FROM D6009-129
- FINISHED LENGTH = 127-82±0.020 (BEFORE BENDING/TRIMMING)


 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- PRIME INSIDE AND OUTSIDE PER DART QSI 005 4.2 PAINT OUTSIDE PER DART 005 4.2
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- ALL DIMENSIONS ARE IN INCHES
- PART IS SYMMETRIC ABOUT CENTERLINE.
- WHEN MACHINING TAPER, RUN-OFF PART AT STOCK, BLEND OUT EDGE LONGITUDINALY. TRANSITION SHOULD BE SMOOTH.
- BEND PROGRESSIVELY WITH A MINIMUM OF 8 PASSES. MAXIMUM TUBE FLATTENING DUE TO BENDING IS 6% BASED ON O.D., EXCEPT UP TO 10% IS ALLOWED IN AREA NOTED. LIQUID PENETRANT INSPECT OUTSIDE SURFACE OF CROSSTUBE PER QSI 038.
- SCRIBE DART PART NUMBER AND BATCH NUMBER ON INNER SURFACE OF TUBE WITH A VIBRATING STYLUS.
- 10) INSTALL D2856-600-1009 ABRASION STRIP WITH A 0.13 (REF) GAP ON BOTTOM SIDE OF CROSSTUBE PER QSI 035.
- 11) EXTREME CARE MUST BE TAKEN TO PROTECT THE OUTSIDE SURFACE OF THE TUBE. THE OUTSIDE SURFACE MUST BE SMOOTH AND FREE FROM SURFACE DEFECTS SUCH AS SCRATCHES, NICKS, OR DENTS. DEFECTS UP TO 0.005" MAY BE BLENDED OUT
- LONGITUDINALLY. CIRCUMFERENTIAL GRIND MARKS ARE UNACCEPTABLE.


 12) APPLY A 0.03" TO 0.06" THICK LAYER OF MAGNOBOND 6398 TO THE SURFACE OF D2896-1
 THAT WILL BE IN CONTACT WITH THE CROSSTUBE. LET CURE FOR 12 HOURS AFTER INSTALLATION AND PRIOR TO PACKAGING.
- 13) INSTALLM 21920-30 CLAMPS (OR -32) WITH D3595-063-570 RUBBER CUSHIONS TO SECURE D2896-1 SUPPORT ON TOP SIDE OF THE CROSSTUBE. ENSURE CLAMPS ARE OPPOSITE CROSSTUBE SUPPORT.
- 14) TORQUE CLAMPS 80 TO 100 IN-LB. ENSURE AT LEAST 1.5 THREADS SHOWING IN SAFETY AND THAT NUT HAS NOT BOTTOMED-OUT AFTER TORQUING.
- 15) INSTALL D3660-1 CUFF AFTER CHEMICAL CONVERSION COAT BUT BEFORE PAINT, WITH A LAYER OF SIKAFLEX-241/-291 OR PROSEAL 890 OR MIL-S-8802 CLASS B2 SEALANT BETWEEN CUFF AND CROSSTUBE. SEAL EDGE OF CUFF TO ENSURE NO GAPS.
 16) TOUCH-UP HOLES WITH CHEMICAL CONVERSION COAT.





	Α	07.07.07	NEW ISSUE	
COPYRIGHT © 2007 BY DART AEROSPACE LTD.	DESIGN P	DRAWN BY	DART	DART AEROSPACE LTD.
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL	CHECKED	APPROVED A	DRAWING NO.	REV.
AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE	Met		D412-664-249	SHEET 1 OF
OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM	DATE		TITLE	SCAL
DART AEROSPACE LTD.	07.07.07		CROSSTUBE (412	2 LOW AFT)







LIQUID PENETRANT TEST REPORT

P- 09830

CUREN											
									PAGE		of <u>/</u>
LIENT	Dart	APE	OSPACE			DATE	Feb 1	5, 2008	TIME	AM 🗆	PM 🗆
	Linda					ACUREN JOB NO.			130		
TTENTION			deen st.			PO/WO No.	572				
DDRESS						Work Location	Haw				
	Hawkes	bury	ontario			ACCEPTANCE STD	ASTM	1413 600	ZůDEV /DAT	re 20	05
ROJECT	212 X-TUE	}£ ,Lau	NARROW AF	Tand	FWE	407 HIGH	AFT X-	UBE ASSETIM	7/7/X	X-10BL	AFT
EM(S) EXAMINED	Job# 366	42 - 31	6644-36	645	-367	62-3677	20 ~ 36 7	73-3700	7-370	110	
			*							Approximately to the second	Observation - Water and Date of the Control of the
OB DESCRIPTI	ION	PROCE	DURE NO. LT-X	XX REV.	/DATE			No. LT-XXXX-XX		E	····
ART NO. 02126	64107-0212	1664307	-130H/3	66430	1- 1070+0	MATERIAL ALLO	DYNEL	ALUMINON	KNESS _		46.00
COPE WE	T FLOU	PRESC	EIVT LIC	2010	PE	NETRAL	<i>T</i> //	ISPECTION	CA	RRIED	001
ON	10075	OF	EXTERA	IAL	SU	FACE					
EST DETAILS											
IETHOD	☼ FLt	JORESCENT	۱ ت	/ISIBLE		WATER WASH		☐ SOLVENT REM	OVABLE		EMULSIFIED
AMILY BRAND	Magne					BLACK LIGHT S/N	8178	X OUTPUT > 100	0 μ W/cm²	☐ AMBIE	
ENETRANT Z	L 67	MINIM	UM DWELL TIME	405		LIGHTING EQUIP.	FLASHLIGH	T U TROUBLELIGH	HT GOT OUTE	201>100 IC	W SURFACE
ENETRANT REMO			UM DRY TIME UM DWELL TIME	>10 10	Min. Min.	OTHER LIGHT METER S/N			CAL DU	EDATE 19	AR OB
EVELOPER SYPE	KDSQ PRINON A		AQUEOUS	DRY		EIGHT WETER GATE					
EST SURFACE	The second secon	QOLOGO .	- / 1402000			·	And the second s				
URFACE CONDITION	and the same of th	OUND	. 🗆 As We	DED		☐ M ACHINED	□ Sнот I			CLEAN BARE	
	ATURE 🗆 < - 4°C		□ - 4°C/ 2	20°F TO 10	0°C/50°F		☑ 10°C/5	50°F то 52°С/125	°F □>	· 52°C/125°	F
ESULTS-	(METR	IC IMP	ERIAL)						3.00 S.00	· · · · · · · · · · · · · · · · · · ·	
nem	CC	MMENTS		ACCEPT	REJECT	~ <i>!\</i>	\times^{\times}				المسمور المالية الأعربية المستبدئة
3664	2: ACCEP	TABLE			-			\times	$\times\!$	\mathbb{Q}	
	4: ACCEP				District Control of the Control of t	<i>?\</i> \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			>< `><		
3664	15: ACCEP	74 BIL	*		Č.						
	B. ACCEA									رود درود درود درود درود درود درود درود	
	O: ACCEPT		<u> </u>			Jun ?		,XX	XX		~~~~ <u>`</u>
	3: ACCEP			-	- Inches				><><	$\leftarrow > <$	
				-			$\geq \leq > \leq$				
3700	19: ACCE F	THOU			L		\times				X.,,X.;
3701	o: Accef	77500						\times	\times_{\swarrow}	\sim	
y , , , , , , , , , , , , , , , , ,	manage was a livery of the form of the company of t		AND THE RESERVE OF THE PROPERTY OF THE PROPERT					>< >< ``	\times		
	and the state of t	magin in the Artis and the Property of the State of the S	**************************************						~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		
		nangging									
										en grande de la composition de la comp	and the second
cope of Services								l d the performance	of the requested s	services It is ex	pressly understood
						no circumstances shall su ased on information and a					
						usea on injormation and a swner/operator retains con the services referred to her					
						ar circumstances by other				o other warrant	y, expressed or
plied, is made or intend	led by Acuren Group Inc.								re careful com Constituti	Control of	
IGNATURES							<i>f</i> = 1 = 1				
LIENT REPRESE	NTATIVE /	Motthe.	V MURD	och_	14/1	Alle MI	COSTO	DTR#	:		
TOUNIOUS 10		- Annual Control of the Control of t	PRINT			SIGNATURE ".		REPORT			
ECHNICIAN (SIGN	ATURE):							REVIEWED BY:			
AME (PRINT):	-ch	ugnon	treder	ick_		2 ^{NO} TECHNICIAN		-	NAME		INITIALS
	CGSB	°1 لي۔ اً Leve	TECHNICIAN SNT LEVEL	c	GSB LEV		LEVEL				
		REG. NO	10560		GSB RE]			
	0000										

